

BELLSOUTH

BellSouth D.C., Inc.
Suite 900
1133 21st Street NW
Washington, DC 20036-3351

steve.long@bellsouth.com

Steven D. Long
Assistant Manager
Federal Regulatory

202 463 4107
Fax 202 463 4631

August 19, 2005

DOCKET FILE COPY ORIGINAL

RECEIVED

AUG 19 2005

Federal Communications Commission
Office of Secretary

Ms. Marlene H. Dortch
Secretary
Federal Communications Commission
445 Twelfth Street, S.W.
Washington, DC 20554

Re: Notices of Network Change Under Rule 51.329(a) CC Docket No. 96-98

Dear Ms. Dortch:

BellSouth Telecommunications, Inc. ("BellSouth") hereby submits the attached original and two copies of its Notices of Network Change Under Rule 51.329(a) in accordance with the requirements set forth in the Commission's Second Report and Order and Memorandum Opinion and Order released August 8, 1996, in CC Docket No. 96-98. A description of the network change is provided below:


Number	Type of Change Planned	Location of Change
20050122	Replacing Copper with Fiber	Miami, FL
20050123 Revision 20040144	Replacing Copper with Fiber	Miami, FL
20050124 Revision 20040363	Replacing Copper with Fiber	Hialeah, FL

As required, one paper copy and one diskette copy is being submitted to the Chief of the Common Carrier Bureau's Network Services Division. A copy of the notice is also available at:

<http://www.interconnection.bellsouth.com/notifications/network/index.html>

Should you have any questions regarding this submission, please contact me at (202) 463-4107.

Sincerely,



Steve Long

Attachments

cc: Julie Veach (with diskette)

No. of Copies rec'd 0 + 2
Carmell Weathers (with diskette)

Notice of Network Change – Miami, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: Second Quarter of 2006

Location of Changes: THE BUILDING LOCATED AT 2200 NW 54TH ST.

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth will have no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and the ability of the competitive carrier to provide DSL service may be affected.

Contact: <u>Technical questions</u>	Gláucio T. Pessoa, P.E.
relating to this change	9101 SW 24 th Av
should be directed to:	Miami, Florida 33165
	Phone: (305) 222-8237

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 1-888-557-0667

Outside BellSouth region: 1-800-786-7619

Fax: 1-205-321-2191

Attachment: 1

ADDRESS LIST

Below is a list of addresses that may be impacted by a conversion from copper-fed to fiber-fed carrier for wirecenter "miamflal" sorted by hno and street.

HOUSE NUMBER	STREET	UNIT	BUILDING
5401	nw 22nd av		
5401	nw 22nd av	shk	
2200	nw 41st st		
2200	nw 46th st		
2275	nw 46th st	1-2	
2275	nw 46th st	23-	
2200	nw 54th st		
2200	nw 54th st	1001	
2200	nw 54th st	1002	
2200	nw 54th st	1003	
2200	nw 54th st	1004	
2200	nw 54th st	1005	
2200	nw 54th st	1006	
2200	nw 54th st	1007	
2200	nw 54th st	1008	
2200	nw 54th st	1009	
2200	nw 54th st	1010	
2200	nw 54th st	1011	
2200	nw 54th st	1012	
2200	nw 54th st	1013	
2200	nw 54th st	102	
2200	nw 54th st	103	
2200	nw 54th st	104	
2200	nw 54th st	105	
2200	nw 54th st	1101	
2200	nw 54th st	1102	
2200	nw 54th st	1103	
2200	nw 54th st	1104	
2200	nw 54th st	1105	
2200	nw 54th st	1106	
2200	nw 54th st	1107	
2200	nw 54th st	1108	
2200	nw 54th st	1109	
2200	nw 54th st	111	
2200	nw 54th st	1110	
2200	nw 54th st	1111	
2200	nw 54th st	1112	
2200	nw 54th st	1113	
2200	nw 54th st	1201	
2200	nw 54th st	1202	
2200	nw 54th st	1203	
2200	nw 54th st	1204	
2200	nw 54th st	1205	

2200	nw 54th st	1206	
2200	nw 54th st	1207	
2200	nw 54th st	1208	
2200	nw 54th st	1209	
2200	nw 54th st	1210	
2200	nw 54th st	1211	
2200	nw 54th st	1212	
2200	nw 54th st	1213	
2200	nw 54th st	140	
2200	nw 54th st	1401	
2200	nw 54th st	1402	
2200	nw 54th st	1403	
2200	nw 54th st	1404	
2200	nw 54th st	1405	
2200	nw 54th st	1406	
2200	nw 54th st	1407	
2200	nw 54th st	1408	
2200	nw 54th st	1409	
2200	nw 54th st	1410	
2200	nw 54th st	1411	
2200	nw 54th st	1412	
2200	nw 54th st	1413	
2200	nw 54th st	150	
2200	nw 54th st	1501	
2200	nw 54th st	1502	
2200	nw 54th st	1503	
2200	nw 54th st	1504	
2200	nw 54th st	1505	
2200	nw 54th st	1506	
2200	nw 54th st	1507	
2200	nw 54th st	1508	
2200	nw 54th st	1509	
2200	nw 54th st	1510	
2200	nw 54th st	1511	
2200	nw 54th st	1512	
2200	nw 54th st	1513	
2200	nw 54th st	160	
2200	nw 54th st	1601	
2200	nw 54th st	1602	
2200	nw 54th st	1603	
2200	nw 54th st	1604	
2200	nw 54th st	1605	
2200	nw 54th st	1606	
2200	nw 54th st	1607	
2200	nw 54th st	1608	
2200	nw 54th st	1609	
2200	nw 54th st	1610	
2200	nw 54th st	1611	

2200	nw 54th st	1612	
2200	nw 54th st	1613	
2200	nw 54th st	1701	
2200	nw 54th st	1702	
2200	nw 54th st	1703	
2200	nw 54th st	1704	
2200	nw 54th st	1705	
2200	nw 54th st	1706	
2200	nw 54th st	1707	
2200	nw 54th st	1708	
2200	nw 54th st	1709	
2200	nw 54th st	1710	
2200	nw 54th st	1711	
2200	nw 54th st	1712	
2200	nw 54th st	1713	
2200	nw 54th st	201	
2200	nw 54th st	202	
2200	nw 54th st	203	
2200	nw 54th st	204	
2200	nw 54th st	205	
2200	nw 54th st	206	
2200	nw 54th st	207	
2200	nw 54th st	208	
2200	nw 54th st	209	
2200	nw 54th st	210	
2200	nw 54th st	211	
2200	nw 54th st	212	
2200	nw 54th st	213	
2200	nw 54th st	301	
2200	nw 54th st	302	
2200	nw 54th st	303	
2200	nw 54th st	304	
2200	nw 54th st	305	
2200	nw 54th st	306	
2200	nw 54th st	307	
2200	nw 54th st	308	
2200	nw 54th st	309	
2200	nw 54th st	310	
2200	nw 54th st	311	
2200	nw 54th st	312	
2200	nw 54th st	313	
2200	nw 54th st	401	
2200	nw 54th st	402	
2200	nw 54th st	403	
2200	nw 54th st	404	
2200	nw 54th st	405	
2200	nw 54th st	406	
2200	nw 54th st	407	

2200	nw 54th st	408	
2200	nw 54th st	409	
2200	nw 54th st	410	
2200	nw 54th st	411	
2200	nw 54th st	412	
2200	nw 54th st	413	
2200	nw 54th st	501	
2200	nw 54th st	502	
2200	nw 54th st	503	
2200	nw 54th st	504	
2200	nw 54th st	505	
2200	nw 54th st	506	
2200	nw 54th st	507	
2200	nw 54th st	508	
2200	nw 54th st	509	
2200	nw 54th st	510	
2200	nw 54th st	511	
2200	nw 54th st	512	
2200	nw 54th st	513	
2200	nw 54th st	601	
2200	nw 54th st	602	
2200	nw 54th st	603	
2200	nw 54th st	604	
2200	nw 54th st	605	
2200	nw 54th st	606	
2200	nw 54th st	607	
2200	nw 54th st	608	
2200	nw 54th st	609	
2200	nw 54th st	610	
2200	nw 54th st	611	
2200	nw 54th st	612	
2200	nw 54th st	613	
2200	nw 54th st	701	
2200	nw 54th st	702	
2200	nw 54th st	703	
2200	nw 54th st	704	
2200	nw 54th st	705	
2200	nw 54th st	706	
2200	nw 54th st	707	
2200	nw 54th st	708	
2200	nw 54th st	709	
2200	nw 54th st	710	
2200	nw 54th st	711	
2200	nw 54th st	712	
2200	nw 54th st	713	
2200	nw 54th st	715	
2200	nw 54th st	801	
2200	nw 54th st	802	

2200	nw 54th st	803	
2200	nw 54th st	804	
2200	nw 54th st	805	
2200	nw 54th st	806	
2200	nw 54th st	807	
2200	nw 54th st	808	
2200	nw 54th st	809	
2200	nw 54th st	810	
2200	nw 54th st	811	
2200	nw 54th st	812	
2200	nw 54th st	813	
2200	nw 54th st	901	
2200	nw 54th st	902	
2200	nw 54th st	903	
2200	nw 54th st	904	
2200	nw 54th st	905	
2200	nw 54th st	906	
2200	nw 54th st	907	
2200	nw 54th st	908	
2200	nw 54th st	909	
2200	nw 54th st	910	
2200	nw 54th st	911	
2200	nw 54th st	912	
2200	nw 54th st	913	
2200	nw 54th st	a	
2200	nw 54th st	elevatr	
2200	nw 54th st	mngmnt ofc	
2200	nw 54th st	penth rado	
2200	nw 54th st	roof	
2200	nw 54th st	roof sn	
2250	nw 54th st		

**Revision to Notice of Network Change – Miami, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems
Carrier**

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment to the revised notification contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: First Quarter of 2006

Notice of Network Change:

Notice of Network Change ND20040144, originally posted on July 13, 2004, regarding Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems in Miami, FL.

Issue 3: Reason for Revision:

Due to the complexity of the work required and due to the current workload assigned to construction resources, the completion of this work has been rescheduled for the first quarter of 2006.

For further information please review the revised Notice of Network Change.

Revised - Notice of Network Change – Miami, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: First Quarter of 2006

Location of Changes: AREA DELIMITED BY NW 106TH ST TO THE NORTH, NW 37TH AV TO THE WEST, NW 103RD ST TO THE SOUTH AND NW 32ND AV TO THE EAST.

Description of Change Planned: Copper Facilities will be replaced with Fiber Optic cable and Digital Loop Carrier systems.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth will have no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and the ability of the competitive carrier to provide DSL service may be affected.

Contact: <u>Technical questions</u> relating to this change should be directed to:	Gláucio T. Pessoa, P.E. 9101 SW 24 th Av Miami, Florida 33165 Phone: (305) 222-8237
---	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 1-888-557-0667

Outside BellSouth region: 1-800-786-7619
Fax: 1-205-321-2191

Attachment: 1

Notice of Network Change Under Rule 51.329(a)
Notification No. ND20040144
Issue Date: July 13, 2004
Issued Date 2: January 7, 2005
Issued Date 3: August 15, 2005

ADDRESS LIST

Below is a list of addresses that may be impacted by a conversion from copper-fed to fiber-fed carrier for wirecenter "miamflns" sorted by hno and street.

HOUSE NUMBER	STREET	UNIT	BLDG
3215	nw 103rd st		
3252	nw 103rd st		
3267	nw 103rd st		
3267	nw 103rd st	rr	
3267	nw 103rd st	side	
3285	nw 103rd st		
3291	nw 103rd st		
3291	nw 103rd st		4
3291	nw 103rd st		5
3291	nw 103rd st	efcny	
3291	nw 103rd st	rr	
3310	nw 103rd st		
3311	nw 103rd st		
3331	nw 103rd st		
3415	nw 103rd st		
3415	nw 103rd st	efncy	
3415	nw 103rd st	rr	
3501	nw 103rd st		
3505	nw 103rd st		
3515	nw 103rd st		
3515	nw 103rd st	rr	
3561	nw 103rd st		
3565	nw 103rd st		
3565	nw 103rd st	efcny	
3567	nw 103rd st		
3567	nw 103rd st	rr	
3573	nw 103rd st		
3573	nw 103rd st	side	
3573	nw 103rd st	trlr	
3575	nw 103rd st		
3575	nw 103rd st	rr	
3601	nw 103rd st		
3665	nw 103rd st		
3675	nw 103rd st		
3677	nw 103rd st		
2625	nw 106th st		3
3201	nw 106th st		
3201	nw 106th st	effncy	
3210	nw 106th st		
3210	nw 106th st	efcny	
3211	nw 106th st		
3211	nw 106th st	efncy	
3213	nw 106th st		

3213	nw 106th st	rr
3213	nw 106th st	side
3225	nw 106th st	
3226	nw 106th st	
3226	nw 106th st	side
3235	nw 106th st	
3235	nw 106th st	side
3236	nw 106th st	
3236	nw 106th st	efcny
3245	nw 106th st	
3245	nw 106th st	efcny
3261	nw 106th st	
3265	nw 106th st	
3271	nw 106th st	
3275	nw 106th st	
3281	nw 106th st	
3285	nw 106th st	
3291	nw 106th st	ef
3295	nw 106th st	
3295	nw 106th st	efcny
3295	nw 106th st	frnt
3295	nw 106th st	1
3297	nw 106th st	
3299	nw 106th st	
3300	nw 106th st	1
3300	nw 106th st	2
3300	nw 106th st	3
3300	nw 106th st	4
3300	nw 106th st	6
3300	nw 106th st	8
3300	nw 106th st	9
3300	nw 106th st	frnt
3300	nw 106th st	sid
3301	nw 106th st	
3321	nw 106th st	
3321	nw 106th st	rr
3321	nw 106th st	side
3341	nw 106th st	
3341	nw 106th st	efncy
3355	nw 106th st	
3355	nw 106th st	rr
3400	nw 106th st	
3400	nw 106th st	side
3401	nw 106th st	
3401	nw 106th st	side
3411	nw 106th st	
3413	nw 106th st	
3413	nw 106th st	rr
3421	nw 106th st	
3421	nw 106th st	dupl frnt

3421	nw 106th st	dupl rr
3423	nw 106th st	
3423	nw 106th st	rr
3425	nw 106th st	
3435	nw 106th st	
3500	nw 106th st	
3501	nw 106th st	
3501	nw 106th st	rr
3502	nw 106th st	
3503	nw 106th st	
3503	nw 106th st	dupl
3511	nw 106th st	
3511	nw 106th st	rr
3513	nw 106th st	rear
3521	nw 106th st	
3521	nw 106th st	eff
3523	nw 106th st	
3531	nw 106th st	
3531	nw 106th st	rr
3531	nw 106th st	side
3531	nw 106th st	trl
3533	nw 106th st	
3533	nw 106th st	left
3537	nw 106th st	
3537	nw 106th st	efncy
3537	nw 106th st	rear
3551	nw 106th st	
3551	nw 106th st	rear
3560	nw 106th st	
3560	nw 106th st	side
3561	nw 106th st	
3561	nw 106th st	rr
3571	nw 106th st	
3575	nw 106th st	
3601	nw 106th st	
3603	nw 106th st	
3624	nw 106th st	
3624	nw 106th st	efcny
3625	nw 106th st	
3625	nw 106th st	1
3625	nw 106th st	2
3625	nw 106th st	3
3625	nw 106th st	4
3625	nw 106th st	5
3627	nw 106th st	
3627	nw 106th st	cell sites
3631	nw 106th st	
3635	nw 106th st	
3642	nw 106th st	
3668	nw 106th st	

3668	nw 106th st	rr
3685	nw 106th st	
3685	nw 106th st	shop
10298	nw 32nd av	constr ste
10324	nw 32nd av	
10324	nw 32nd av	efncy
10330	nw 32nd av	
10350	nw 32nd av	
10400	nw 32nd av	
10400	nw 32nd av	side
10416	nw 32nd av	
10426	nw 32nd av	
10426	nw 32nd av	efcny rr
10426	nw 32nd av	efncyrr
10426	nw 32nd av	rr
10426	nw 32nd av	side
10440	nw 32nd av	
10440	nw 32nd av	efcny
10500	nw 32nd av	
10510	nw 32nd av	
10528	nw 32nd av	
10536	nw 32nd av	
10300	nw 32nd ct	
10300	nw 32nd ct	efncy
10320	nw 32nd ct	
10321	nw 32nd ct	
10334	nw 32nd ct	
10337	nw 32nd ct	
10337	nw 32nd ct	side
10337	nw 32nd ct	side r
10338	nw 32nd ct	
10345	nw 32nd ct	
10400	nw 32nd ct	
10400	nw 32nd ct	efcny
10400	nw 32nd ct	efficiency
10400	nw 32nd ct	rr
10405	nw 32nd ct	
10410	nw 32nd ct	
10417	nw 32nd ct	
10429	nw 32nd ct	
10429	nw 32nd ct	1
10429	nw 32nd ct	2
10429	nw 32nd ct	3
10429	nw 32nd ct	side
10430	nw 32nd ct	
10440	nw 32nd ct	
10440	nw 32nd ct	efcny rr
10441	nw 32nd ct	
10441	nw 32nd ct	efcny
10441	nw 32nd ct	side

10500	nw 32nd ct	
10500	nw 32nd ct	rr
10501	nw 32nd ct	
10506	nw 32nd ct	
10506	nw 32nd ct	efcny
10510	nw 32nd ct	
10515	nw 32nd ct	
10525	nw 32nd ct	
10320	nw 32nd pl	
10321	nw 32nd pl	
10321	nw 32nd pl	efcny
10321	nw 32nd pl	1
10330	nw 32nd pl	
10335	nw 32nd pl	
10340	nw 32nd pl	
10340	nw 32nd pl	rr
10341	nw 32nd pl	
10351	nw 32nd pl	
10355	nw 32nd pl	
10358	nw 32nd pl	
10358	nw 32nd pl	efcny
10358	nw 32nd pl	rr
10365	nw 32nd pl	
10379	nw 32nd pl	
10379	nw 32nd pl	efcny
10379	nw 32nd pl	rr
10416	nw 32nd pl	
10416	nw 32nd pl	efncy
10416	nw 32nd pl	frnt
10416	nw 32nd pl	1
10420	nw 32nd pl	
10430	nw 32nd pl	
10437	nw 32nd pl	
10500	nw 32nd pl	
10501	nw 32nd pl	
10510	nw 32nd pl	
10510	nw 32nd pl	1
10510	nw 32nd pl	efcny
10510	nw 32nd pl	rear
10517	nw 32nd pl	
10528	nw 32nd pl	
10536	nw 32nd pl	
10321	nw 33rd av	
10330	nw 33rd av	
10337	nw 33rd av	
10337	nw 33rd av	efncy
10340	nw 33rd av	
10340	nw 33rd av	frnt
10340	nw 33rd av	rr
10344	nw 33rd av	

10344	nw 33rd av	rr
10345	nw 33rd av	
10400	nw 33rd av	
10401	nw 33rd av	
10411	nw 33rd av	
10411	nw 33rd av	efcny
10411	nw 33rd av	rr
10420	nw 33rd av	
10421	nw 33rd av	
10424	nw 33rd av	
10429	nw 33rd av	
10429	nw 33rd av	side
10500	nw 33rd av	
10501	nw 33rd av	
10511	nw 33rd av	
10512	nw 33rd av	
10528	nw 33rd av	
10541	nw 33rd av	
10300	nw 34th av	
10311	nw 34th av	
10320	nw 34th av	
10320	nw 34th av	right sde
10321	nw 34th av	
10330	nw 34th av	
10330	nw 34th av	efcny
10330	nw 34th av	side r
10340	nw 34th av	
10345	nw 34th av	
10355	nw 34th av	
10355	nw 34th av	efcny
10355	nw 34th av	efcny r
10355	nw 34th av	rear
10355	nw 34th av	rr
10355	nw 34th av	rr right
10355	nw 34th av	tlr
10400	nw 34th av	
10400	nw 34th av	rr
10400	nw 34th av	side
10413	nw 34th av	
10413	nw 34th av	rr
10420	nw 34th av	
10421	nw 34th av	
10426	nw 34th av	
10429	nw 34th av	
10440	nw 34th av	
10440	nw 34th av	efcny side
10451	nw 34th av	
10451	nw 34th av	efcny
10451	nw 34th av	efncy
10500	nw 34th av	

10516	nw 34th av	
10520	nw 34th av	
10520	nw 34th av	efcny
10528	nw 34th av	
10545	nw 34th av	
10545	nw 34th av	rr
10565	nw 34th av	
10575	nw 34th av	
10585	nw 34th av	
10305	nw 35th av	
10305	nw 35th av	rr
10320	nw 35th av	
10320	nw 35th av	efcny
10323	nw 35th av	
10323	nw 35th av	efcny
10330	nw 35th av	
10330	nw 35th av	frnt
10330	nw 35th av	rr
10332	nw 35th av	
10340	nw 35th av	
10340	nw 35th av	efcny
10340	nw 35th av	sid
10343	nw 35th av	
10358	nw 35th av	
10358	nw 35th av	side frnt
10358	nw 35th av	side rr
10368	nw 35th av	
10368	nw 35th av	rr
10401	nw 35th av	
10401	nw 35th av	efcny
10401	nw 35th av	grge
10405	nw 35th av	
10415	nw 35th av	
10415	nw 35th av	efcny
10415	nw 35th av	efcy
10425	nw 35th av	
10430	nw 35th av	
10430	nw 35th av	efcny l
10430	nw 35th av	efncy r
10430	nw 35th av	rr
10441	nw 35th av	
10441	nw 35th av	rr
10441	nw 35th av	trl
10450	nw 35th av	
10500	nw 35th av	
10500	nw 35th av	efcny
10501	nw 35th av	
10501	nw 35th av	efncy
10501	nw 35th av	rr
10511	nw 35th av	

10511	nw 35th av	efcny
10511	nw 35th av	efncy
10516	nw 35th av	
10516	nw 35th av	efcny
10516	nw 35th av	efcny rr
10520	nw 35th av	
10528	nw 35th av	
10529	nw 35th av	
10529	nw 35th av	b
10529	nw 35th av	rr
10539	nw 35th av	
10300	nw 35th ct	
10300	nw 35th ct	efcny
10302	nw 35th ct	
10302	nw 35th ct	efcny
10302	nw 35th ct	efncy
10303	nw 35th ct	
10305	nw 35th ct	
10321	nw 35th ct	
10325	nw 35th ct	
10325	nw 35th ct	rr
10330	nw 35th ct	
10330	nw 35th ct	efcny
10335	nw 35th ct	
10340	nw 35th ct	
10340	nw 35th ct	front
10340	nw 35th ct	rr
10345	nw 35th ct	
10350	nw 35th ct	
10402	nw 35th ct	
10405	nw 35th ct	
10405	nw 35th ct	efcny
10415	nw 35th ct	
10416	nw 35th ct	
10421	nw 35th ct	
10430	nw 35th ct	
10430	nw 35th ct	rr
10440	nw 35th ct	
10441	nw 35th ct	
10500	nw 35th ct	
10516	nw 35th ct	
10521	nw 35th ct	
10525	nw 35th ct	
10529	nw 35th ct	
10529	nw 35th ct	efcny side
10530	nw 35th ct	
10530	nw 35th ct	efcny
10530	nw 35th ct	rr
10540	nw 35th ct	
10540	nw 35th ct	efcny righ

10300	nw 35th pl	
10300	nw 35th pl	efcny
10300	nw 35th pl	rr
10300	nw 35th pl	rr l
10303	nw 35th pl	
10305	nw 35th pl	
10305	nw 35th pl	rr
10320	nw 35th pl	
10320	nw 35th pl	rr
10331	nw 35th pl	
10340	nw 35th pl	
10341	nw 35th pl	
10341	nw 35th pl	efcny side
10348	nw 35th pl	
10350	nw 35th pl	
10351	nw 35th pl	
10351	nw 35th pl	efcny l
10351	nw 35th pl	frnt r
10351	nw 35th pl	left
10351	nw 35th pl	rr
10400	nw 35th pl	
10400	nw 35th pl	rear
10400	nw 35th pl	rr
10401	nw 35th pl	
10403	nw 35th pl	
10416	nw 35th pl	
10420	nw 35th pl	
10421	nw 35th pl	
10421	nw 35th pl	frnt
10421	nw 35th pl	rr l
10423	nw 35th pl	
10423	nw 35th pl	efncy
10423	nw 35th pl	rear
10423	nw 35th pl	rr
10430	nw 35th pl	
10430	nw 35th pl	efc
10430	nw 35th pl	efcny
10430	nw 35th pl	rr
10430	nw 35th pl	side
10431	nw 35th pl	
10431	nw 35th pl	414
10431	nw 35th pl	e
10431	nw 35th pl	rr
10431	nw 35th pl	side l
10440	nw 35th pl	
10500	nw 35th pl	
10501	nw 35th pl	
10501	nw 35th pl	efcny
10515	nw 35th pl	
10515	nw 35th pl	efcny

10515	nw 35th pl	side
10516	nw 35th pl	
10530	nw 35th pl	
10530	nw 35th pl	l side
10530	nw 35th pl	rr
10535	nw 35th pl	
10535	nw 35th pl	rr
10541	nw 35th pl	
10300	nw 36th ct	
10300	nw 36th ct	1
10300	nw 36th ct	2
10300	nw 36th ct	3
10300	nw 36th ct	efcny
10300	nw 36th ct	frnt
10300	nw 36th ct	frnt mdl
10300	nw 36th ct	side
10320	nw 36th ct	
10320	nw 36th ct	rear
10325	nw 36th ct	
10325	nw 36th ct	efcny
10325	nw 36th ct	rr
10330	nw 36th ct	
10335	nw 36th ct	
10335	nw 36th ct	effncy
10340	nw 36th ct	
10340	nw 36th ct	bth b-75
10340	nw 36th ct	rear
10345	nw 36th ct	
10345	nw 36th ct	rr
10400	nw 36th ct	
10401	nw 36th ct	
10401	nw 36th ct	side
10418	nw 36th ct	
10418	nw 36th ct	rr
10419	nw 36th ct	
10419	nw 36th ct	frnt
10419	nw 36th ct	rear
10419	nw 36th ct	rr
10419	nw 36th ct	side
10419	nw 36th ct	side r
10420	nw 36th ct	
10420	nw 36th ct	efcny rr l
10421	nw 36th ct	
10421	nw 36th ct	efcny
10421	nw 36th ct	efncy
10430	nw 36th ct	
10430	nw 36th ct	rr
10431	nw 36th ct	
10431	nw 36th ct	apt
10431	nw 36th ct	r

10431	nw 36th ct	side
10500	nw 36th ct	
10510	nw 36th ct	
10510	nw 36th ct	efcny
10510	nw 36th ct	rr
10517	nw 36th ct	
10517	nw 36th ct	r
10517	nw 36th ct	side
10519	nw 36th ct	
10528	nw 36th ct	
10529	nw 36th ct	
10529	nw 36th ct	sid
10529	nw 36th ct	side
10300	nw 36th pl	
10301	nw 36th pl	
10320	nw 36th pl	
10321	nw 36th pl	
10330	nw 36th pl	
10330	nw 36th pl	frnt hse
10331	nw 36th pl	
10340	nw 36th pl	
10344	nw 36th pl	
10391	nw 36th pl	
10400	nw 36th pl	
10400	nw 36th pl	efcny
10400	nw 36th pl	side
10401	nw 36th pl	
10401	nw 36th pl	efcny
10401	nw 36th pl	rr
10401	nw 36th pl	rr r
10410	nw 36th pl	
10410	nw 36th pl	efncy
10410	nw 36th pl	rr
10412	nw 36th pl	
10412	nw 36th pl	efcny rr
10412	nw 36th pl	rr
10417	nw 36th pl	
10417	nw 36th pl	rr
10419	nw 36th pl	
10420	nw 36th pl	
10421	nw 36th pl	
10421	nw 36th pl	r
10423	nw 36th pl	
10423	nw 36th pl	efncy
10431	nw 36th pl	
10440	nw 36th pl	
10500	nw 36th pl	
10500	nw 36th pl	efcny rear
10500	nw 36th pl	efncy
10500	nw 36th pl	rr

10503	nw 36th pl	
10515	nw 36th pl	
10515	nw 36th pl	efcny
10515	nw 36th pl	efncy
10515	nw 36th pl	rear
10515	nw 36th pl	rr
10516	nw 36th pl	
10516	nw 36th pl	dupl rr
10516	nw 36th pl	left
10520	nw 36th pl	
10520	nw 36th pl	frnt
10520	nw 36th pl	rr
10529	nw 36th pl	
10530	nw 36th pl	
10530	nw 36th pl	rr
10321	nw 37th av	
10330	nw 37th av	
10339	nw 37th av	
10339	nw 37th av	rr
10340	nw 37th av	
10340	nw 37th av	trl
10349	nw 37th av	
10350	nw 37th av	
10355	nw 37th av	
10355	nw 37th av	side
10369	nw 37th av	
10369	nw 37th av	l
10369	nw 37th av	r
10369	nw 37th av	rr
10381	nw 37th av	
10381	nw 37th av	rr
10393	nw 37th av	dupl
10393	nw 37th av	dupl b
10393	nw 37th av	dupl c
10393	nw 37th av	duplex
10393	nw 37th av	frnt
10393	nw 37th av	rr
10393	nw 37th av	side l
10425	nw 37th av	
10485	nw 37th av	
10501	nw 37th av	
10517	nw 37th av	
10517	nw 37th av	efcny
10517	nw 37th av	efcny b
10529	nw 37th av	
10541	nw 37th av	
10600	nw 37th av	trl

**Revision to Notice of Network Change – Hialeah, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems
Carrier**

BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment to the revised notification contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: Second Quarter of 2006

Notice of Network Change:

Notice of Network Change ND20040363, originally posted on January 28, 2005, regarding Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems in Hialeah, FL.

Issue 2: Reason for Revision:

Due to the complexity of the work required and due to the current workload assigned to construction resources, the completion of this work has been rescheduled for the second quarter of 2006.

For further information please review the revised Notice of Network Change.

**Revised - Notice of Network Change – Hialeah, Florida
Replacing Copper Facilities with Fiber and Digital Loop Carrier Systems**

Carrier
BellSouth Telecommunications, Inc.
675 West Peachtree Street NE
Atlanta, Georgia 30375

Attachment contains addresses affected by the removal of copper facilities.

Date Changes are to Occur: Second Quarter of 2006

Location of Changes: OFFICE BUILDING AT 9400 NW 37TH AV.

Description of Change Planned: Copper Facilities will be replaced with Digital Loop Carrier Facilities.

Description of Reasonably Foreseeable Impact of the Planned Change: After this work is completed, metallic facilities from the Central Office to the affected area will no longer be available. Unbundled loops that are defined as compatible with Digital Loop Carrier (DLC), e.g., those defined to transport POTS-grade service, will be transferred to the new DLC system. Competitive carriers employing unbundled loops that are defined to require metallic facilities, e.g., Digital Subscriber Line (DSL) or line sharing circuits, will be notified individually. This notification is intended to allow the affected carrier to convert the circuit to one compatible with DLC.

It should be noted that if a competitive carrier obtains an unbundled loop that has been defined to transport POTS-grade service, but then utilizes the POTS-grade loop to provide DSL service, BellSouth has no knowledge of the presence of DSL. In such a case, BellSouth has no basis to notify the carrier and there will be no means to continue the DSL service.

Contact: <u>Technical questions</u> relating to this change should be directed to:	Gláucio T. Pessoa, P.E. 9101 SW 24th St Miami, FL 33165 Phone: (305) 222-8237
---	---

All other questions or concerns regarding this change should be referred to your BellSouth account team representative, the Interexchange Carrier Service Center (ICSC) or the Local Interconnection Service Center (LISC). Payphone Service Providers should contact the following numbers with questions or concerns:

In the BellSouth region: 1-888-557-0667

Outside BellSouth region: 1-800-786-7619

Fax: 1-205-321-2191

Attachment: 1

Notice of Network Change Under Rule 51.329(a)
Notification No. ND20040363
Issue Date: January 28, 2005
Issue Date 2: August 16, 2005

ADDRESS LIST

Below is a list of addresses that may be impacted by a conversion from copper-fed to fiber-fed carrier for wirecenter "miamflns" sorted by hno and street.

HOUSE NUMBER	STREET	UNIT	BLDG
9400	nw 37th av	1	
9400	nw 37th av		
9400	nw 37th av		a
9400	nw 37th av	a	
9400	nw 37th av	claim agnt	
9400	nw 37th av	comm	
9400	nw 37th av	dieselshop	
9400	nw 37th av	equip	
9400	nw 37th av	freght agt	
9400	nw 37th av	ofc	
9400	nw 37th av	rla	
9400	nw 37th av	rmc	
9400	nw 37th av	store 16	
9400	nw 37th av	tel	
9400	nw 37th av	tele	
9400	nw 37th av	trl 1	
9400	nw 37th av	trl 2	
9400	nw 37th av	trl 3	